



ACCESSIBILITY AUDIT for

Photo Album

produced with



automated compliance
assessment & reporting
for disability access



A Building A Level 1
7 Stairwell North, Level 1

Img 1 1699




Lctn 25

Handrail Step(s)/Stairway

A Building A Level 1
2 Stairwell North, Level 1

Img 2 2390




Lctn 25

Handrail

B Building B Level 1
3 Stairwell Lvl 1

Img 3 2559




Lctn 86

Handrail Step(s)/Stairway

B Building B Level 2
4 Stairwell Lvl 2

Img 4 1164




Lctn 97

Emergency Egress feature Hazard Step(s)/Stairway

B Building B Level 2
5 Fire escape stair from B2 to Plaza 1

Img 5 2465



Lctn 1385

Handrail Step(s)/Stairway

D Building D Level 2
6 Stairwell North, Lvl. 1

Img 7 1790



Lctn 1459

Step(s)/Stairway

E Building E Level 2
7 Stairwell

Img 8 1051



Lctn 274

Step(s)/Stairway

E Building E Level 1
8 Vestibule East end of Passage

Img 8 1051



Lctn 237

Step(s)/Stairway

E Building E Level 2
9 Stairwell

Img 9 1074



Lctn 274

Step(s)/Stairway